

Revised Exhibit I

Tavares





(WEST CENTRAL)

The Tavares Readiness Center currently has barbed wire fencing surrounding the western, eastern and southern perimeters while the northern perimeter is opened and exposed to vehicle and pedestrian traffic.

8 ft. high security barbed wire top chain link perimeter fencing with anti-ramming cables is being requested to help enclose the entire perimeter. This fencing will start on the northwestern boundary, continue east parallel to Woodland Road and stop at the northeastern boundary line. From there the fencing will continue south, run west behind the motor pool, stop at the northwest boundary line and continue back north connecting to the fencing at the northwest boundary. The current barbed wire fencing at the eastern, western and southern locations will be removed.

A single cantilever sliding gate will be placed at two locations north of the Armory parallel to Woodleaf Drive with no more than 2 inch spacing between the bottom of the gate and ground. **NO K12/K8 fencing/gates will be placed at this site.**

Tavares

- Existing chain-link fencing 
- Existing chain-link gate 
- Proposed security barbed wire top chain-link fencing with anti-ramming cables 
- Proposed single cantilever sliding gates 
- Fencing to be removed 