

## **Tavares (WEST CENTRAL)**

The Tavares Readiness Center currently has barbed wire fencing surrounding the western, eastern and southern perimeters. The front of the Armory is opened and exposed. An estimated request of 1100 linear ft. (8 ft. high) security barbed wire top chain link fencing with anti-ramming cables will enclose the entire Armory. This fencing will extend north protecting the front of the Armory parallel to Woodland Road and extend to the eastern, western and southern perimeter. The current barbed wire fencing at the eastern, western and southern locations will be removed. A single cantilever sliding gate will be placed at two locations north of the Armory parallel to Woodleaf Drive with no more than 2 inch spacing between the bottom of the gate and ground. **NO K12/K8 fencing/gates will be placed at this site.**

# Tavares

Existing chain-link fencing ———  
Existing chain-link gate ———  
Proposed security barbed wire top chain-link fencing with anti-ramming cables - - -  
Proposed single cantilever sliding gates ■■■  
Fencing to be removed - - -

Proposed security barbed wire chain-link fence and gate with anti-ramming cables (1100 linear ft. 8 ft. high)