## Bidder's Pre-Qualification Status 18-ITB-001-SS Fuller Warren Building - Chiller Replacement H2E #1745

VENDOR NAME	Attended the Mandatory Pre- Response Site Visit per Section B.7 of the ITB.	Current State Contractor license certification or registration as required under Florida Statutes.	Current Corporate Charter registration, if the potential bidder is a domestic (Florida) corporation, or authority to transact business if the potential bidder is a foreign (non-Florida) corporation, as may be required by Florida law.
Air Mechanical & Service Corp.	Х	Х	Х
Thermaserve Inc	N	Х	Х
ARKEST LLC	N	Х	Х
Carrier Corporation	N	Expired	Expired

Shaded area indicates Vendor did not meet Mandatory Prequalification Status.

X - Area indicates documents were received by deadline for Prequalification Status.